10/623846 cofc

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent. No.

: US 6,885,220 B2

Patentee

: Bernhard Engl

Issued

: Apr. 26, 2005

Art Unit

: 2819

Examiner

: Vibol Tan

Title Docket No.

: Current Source Circuit : J&R-1053

Customer No.

: 24131

Certificate JUN 1 4 2005

of Correction

Commissioner for Patents

P.O. Box 1450,

Alexandria, VA 22313-1450

ATTENTION: Decision and Certificate of Correction Branch of the Patent Issue

Division

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT FOR PTO MISTAKE (37 C.F.R.1.322(a))

- Attached, in duplicate, is Form PTO-1050, with one copy suitable for printing.
- The Document where the errors are shown correctly in the application file are:

Claim 3 appears correctly on page 4 of the Amendment filed on November 26, 2004 in the U.S. Patent and Trademark Office.

3. Please send the Certificate to:

Name

: LERNER AND GREENBERG, P.A.

Address: P.O. BOX 2480, HOLLYWOOD, FL 33022-2480

| ☐ Assignment recorded on | wish |
|--------------------------------------------------------------------------|--------------------------------------------------------------|
| Reel: | WERNER H. STEME of authorized person signing REG. NO. 34,956 |
| Frame: | Attorney of Record |
| ☐ Attached is a Recordal of assignmen | Title of authorized person signing |
| Attached is a "CERTIFICATE UNDEI (establishing the right of the assigned | · · · · · · · · · · · · · · · · · · · |
| Date: | |

Under the Paperwork Reduction Act of 1995, no persons are required to repsond to a collection of information unless it displays a valid OMB Control Number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : US 6,885,220 B2

ISSUED : Apr. 26, 2005 INVENTOR(S) : Bernhard Engl

It is certified that an error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 7, line 62, claim 3 should read as follows:

terminals and emitter terminals, during operation of said

MAILING ADDRESS OF SENDER:

PATENT NO. 6,885,220

Lerner and Greenberg P.A. P.O. Box 2480 Hollywood, FL 33020

No. of additional copies

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, P.O. Boc 1450, Alexandria, VA 22313-1450.

Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE

Under the Paperwork Reduction Act of 1995, no persons are required to repsond to a collection of information unless it displays a valid OMB Control Number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO

US 6,885,220 B2

ISSUED

Apr. 26, 2005

INVENTOR(S)

Bernhard Engl

It is certified that an error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 7, line 62, claim 3 should read as follows:

terminals and emitter terminals, during operation of said

MAILING ADDRESS OF SENDER:

PATENT NO. 6,885,220

Lerner and Greenberg P.A. P.O. Box 2480 Hollywood, FL 33020

No. of additional copies

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, P.O. Boc 1450, Alexandria, VA 22313-1450.